

Punch List and Change List
Jack and Danielle Mayer

Note: many of these items are not “fixes” but changes we are requesting.

Version 1.3 4/16 (items 42-53, new)

1. Doors under kitchen sink hit each other on edges.
2. Add two adjustable shelves in each of the entertainment center “flanking” cabinets.
3. Under-sink grate holder
4. Winegard control placement – move to entertainment center if possible. Otherwise box it in the cabinet so that books, etc can be put on it – see me.
5. Polyurethane “wine area” inside of cabinet.
6. 2 extra pantry drawers
7. Remove soap dish in shower. Save for us to move to 2010 trailer.
8. Missing 120v outlet in upper cabinet over instrument area. Place in left wall if possible.
9. Add adjustable shelf in cabinet above pantry area.
10. Trim wardrobe lock sticks a little. One is tight.
11. Switch at Entertainment Center should be dimmer.
12. Move speaker at top of kitchen cabinets (Right, Front speaker) forward to near front of crown molding.
13. Remove coffee table (we don’t need it)
14. Left drawer in island sticks some.
15. Cut ¾” hole through wall into conduit to roof in communications cabinet.
16. Progressive meter missing (backordered).
17. Grout touch-up in kitchen.
18. C-roll toilet room night shade for more privacy.
19. Samsung – only one remote. Should be one for TV and BluRay player? (it was in our document package)
20. Hang towel bars: SEE US FIRST.
21. Clean up caulk in skylight. (minor)
22. Add third step light.
23. Top/Right drawer in bedroom does not extend properly.
24. Left wardrobe door sticks/drag.
25. Tape (outside) on forward side of kitchen slide needs repositioning.
26. Ethernet lines in entertainment center: TV and Sat Receiver are supposed to have separate lines.... (they are there)
27. ?? Are outlets in dining slide on inverter? No – will change in October
28. Fireplace remote? (in document package)
29. Paint touchup....we will mark with tape. (no touchup – amazing)
30. Medallion on valance at rear window not centered.
31. Add wood medallion under multiplex light control in bedroom.

32. Add medallion or other method to dress up the (unused) TV outlets in Bedroom.
33. Leading edge (front) of kitchen slide is not flush. Needs adjusting.
34. Rearmost left-side window leaks.
35. Screen door "hangs" on screw....adjust.
36. Remove excess caulk at roof edge trim at rear.
37. Reposition water filters behind partition.
38. Second sewer tube is missing.
39. In basement: provide a protective cover for multiplex light control, AND for the water lines at manifold that are on the floor area.
40. Magnum inverter remote is damaged. Selection wheel.
41. Basement door on curb side needs adjusting....hard to close door. (not an issue – bulbs compressed with use and is OK)
- 42. Reverse Osmosis under sink runs constantly. It should be plumbed to fill the 3 gallon reservoir tank then shut off. The effect is that it fills the grey tank to overflowing within 24 hrs..control valve is missing.**
- 43. DirecTV sat cabling does not work....probably cable between receiver and Denon, but may be sat input lines. (Operator error- not an issue)**
- 44. Need A/B switch to switch satellite input from roof to utility cabinet lines.**
- 45. Clean up putty smears from refrigerator trim – lower left side.**
- 46. Clean glue off countertops. Clean glue off bottom entry step.**
- 47. Putty minor gap in crown molding at refrigerator. It has pulled apart.**
- 48. Add cover in 2010 Majestic instrument center where generator control panel was removed.**
- 49. Medallion (cherry plate) for step multiplex lights?? (item 31 – partially complete....)**
- 50. Pantry vertical rails (left/front) are not parallel – cannot place drawers in center of pantry.**
- 51. Reprogram entry electronic lock and remote. Lesson on operation.**
- 52. Touch up scratch on Entertainment Center top (we scratched it moving).**
- 53. Add additional puck light under counter, tie to existing lights, location marked with "yellow stickie".**